Maryland Historical Trust

Maryland Inventory of Historic Properties number:

Reviewer, NR Program: Peter E. Kurtze

								U	
The bridge referenced herein was Historic Bridge Inventory, and SI The Trust accepted the Historic E determination of eligibility.	HA provided the Trust wi	th eligi	bility	detern	ninatio	ns in	Februa	ary 20	001.
	MARYLAND HISTOI								
Eligibility RecommendedX_			Eligib	ility N	lot Red	comm	ended		
Criteria: A B C	D Considerations:	A _	_B_	_C _	D	E _	F	_G_	_None
Comments:									
Reviewer, OPS:_Anne E. Bruder				Dat	e:3	April :	2001_		

Date:__3 April 2001

Chap

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. M 46 over Little Monocacy River

<u>Location:</u> Street/Road Name and Number: <u>West Harris Road over Little Monocacy River</u>
City/Town: Barnesville Vicinity X
County: Montgomery
Ownership:State_X_CountyMunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: yes X no
NR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X Metal Girder X Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased
Metal Suspension
Metal Arch

Metal Cantilever	
Concrete	
Concrete ArchConcrete Slab	Concrete Beam
Rigid Frame	
Other Type Name	

Description:

Describe Setting:

Bridge No. M 46 carries West Harris Road north-south over the Little Monocacy River in Montgomery County, Maryland. The bridge approaches are straight and level. There Wbeam guardrails on the approaches. The area around the bridge is rural and wooded.

Describe Superstructure and Substructure:

Bridge No. M 46, built in 1925, is a 27' long single span structure carrying West harris Road over Little Monocacy River. The structure has a clear roadway width of 20'-5" and is posted with a wight limit of 7 tons. The superstructure consists of an asphalt wearing surface over a concrete deck supported by steel stringers. The substructure consists of two concrete abutments. Bridge guardrails consist of steel pipe railings.

The superstructure is in generally good condition. The asphalt wearing surface is deteriorating causing large spalled areas in the concrete in the top slab throughout the entire deck. The underside of the deck has spalls with exposed reinforcing steel typically adjacent to the facia beams. The concrete curbs are cracked at the ends of the bridge adjacent to the embedded rail posts. The pipe railing is bent and distorted in several places. The substructure is generally in fair condition. The abutments and wingwalls have large areas of deteriorated concrete. Approximately 75% of southwest wingwall surface, and 25% of southeast wingwall surface sounds hollow when struck with a hammer, and appears to be severely deteriorating.

Discuss Major Alterations:

There have been no known major alterations.

History:

When Built: 1925

Why Built: Local transportation needs

Who Built: Unknown

Why Altered:

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

__A Events __Person __X C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

It is unknown whether this bridge was constructed in response to significant events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether the construction and/or alteration of this bridge has had significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge is not located in an area which is eligible for historic designation.

Is the bridge a significant example of its type?

This bridge may be a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

This bridge appears to retain integrity of the character defining elements, as defined within the Context Addendum.

Should this bridge be given further study before significance analysis is made and Why?

Further study of this bridge is unnecessary. This bridge is eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Montgomery County

v.d. County Bridge Inspection Files.

Spero, P.A.C. & Company, and Louis Berger & Associates


1994 Historic Bridges in Maryland: Historic Bridge Context.

United States Geological Survey

1970 7.5' Poolesville Quadrangle, photorevised 1978.

Surveyor:

Name: Jason D. Moser Date: September 1995
Organization: State Highway Admin, Telephone: (410) 321-2213
Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory # M: 12-49

LITTLE MONOCACE
Name MHG - WEST HARRIS ROOVER RIVER
County/State Montgomery mp
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description APPROACH NORTH
Number 4 of 26



Inventory # M: 12-49

Name M46 - WEST HARRIS RO OVER LITTLE MONOCACY RIVER
County/State Montoomery / mo
Name of Photographer FRANK JUNIANO
Date 295
Location of Negative SHR
Description ELEVATION WEST
<u> </u>
A
Number 5 of 35



Inventory # M112-49

Name M46-WEST HARRIS ROOVER LITTLE MONOCLACY RIVER
County/State Montoomery mo
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description APPROACH SOUTH
3 4
Number 6 of 36



Inventory # M: 12-49

Name M46-WEST HARRIS RD OVER MONOCACY RIVER
Name 1146-WEST HARRIS KD OVER MONOCACY KIVER
County/State Moratsomery mp
Name of Photographer FRANK JULIANO
Date 2/95
Location of Negative SHA
Description ELEVATION EAST
Number 4 of 30